

[Back](#)

Permit Information

Permit Number:	220271
Permit Date:	07/22/2022
Permit Identifier:	EW 22-271 (Saparov)
Status:	Issued
ADU:	No
Occupancy Change:	No
Occupancy Type:	R-Residential
Division:	3
Owner Name:	Mike Saparov
Date Submitted:	07/22/2022
Date Approved:	07/22/2022
Date Issued:	07/22/2022
Date Finaled:	

Project Description:	Replace rotten wood fence on existing side-yard interior fence. Fence is located outside of front setback and will replace approx...
Property Location:	San Antonio 3 SE of 3th
Block:	HH
Lot:	22
Stormwater Required:	No
Stormwater Meeting Conducted:	
Tree Protection Required:	No
Tree Protection Approval:	
Planning Approval Required:	Yes
Planning Review Approval:	07/22/2022
Revision Number:	
Revision Date Submitted:	
Revision Description:	

Contractors

Owner/Builder - **B - General Building**,
Primary Contact:

Property Information

Parcel #: 010253016000
San Antonio 3 SE of 3th
CARMEL, CA

Uploaded Files

1 file has been uploaded

Files

[Choose Files](#)

[Request An Inspection](#)